



LETTER OF COMPLIANCE

April 8, 2013

Ralph Stiebel
Listing Address:
1099 Lodge Rd.
North Vancouver, BC
V7R 1W7

Dear Mr. Stiebel

We have performed an M-2 scope metal detection scan for a (UST) underground storage tank at the above address.

Due to the results of the scan, this may have included probing and exploratory digging we are confident that there is no underground storage tank buried on the property.



Martin Wouters

Disclaimer

We will only refund the amount charged for our services and will not accept any legal liability in any way for the future discovery of underground oil tanks found under additions added to the original construction of the building, under storage sheds, detached buildings, concreted walkways and slabs which contain rebar or large amounts of metal construction materials.